



CERTIFICATE



This is to certify that

Sayer Lack Mexicana S.A. de C.V.

Planta Resinas 0330

Francisco Villa No. 2
Col. Centro Tlalnepantla
C.P. 54000, Tlalnepantla, Estado de México
México

IATF USI T4FFWL

has implemented and maintains a **Quality Management System**.

Scope:

Manufacturing of Solvents and Catalysts

An audit, conducted and documented in a report, has verified that this quality management system fulfills the requirements of the following international automotive standard and IATF Rules 6th Edition:

IATF 16949:2016

(without product design)

Certificate registration no.	70003360 IATF25
Issuing date	2026-01-14
This certificate is valid until	2029-01-13
IATF No.	0594857



For and on behalf of DQS

Ingo M. Rübenach
Managing Director, DQS Holding GmbH

Nurani S. Venkatachalam
Director-Corporate Automotive Program, DQS Holding GmbH





Annex to certificate registration no.: 70003360 IATF25
IATF-No.: 0594857

Sayer Lack Mexicana S.A. de C.V.

Planta Resinas 0330

Francisco Villa No. 2
Col. Centro Tlalnepantla
C.P. 54000, Tlalnepantla, Estado de México
México



Remote Location

Scope

70003088

Sayer Lack Mexicana S.A. de C.V.

Km.13.7 Carretera Libre Querétaro-Celaya
C.P. 38513, Apaseo el Alto, Guanajuato
México

IATF USI LYMS3W

Purchasing; Supplier Management; Quality System Management; Management Review; Strategic Planning; Information Technology; Internal Audit Management; Distribution.

70003358

Sayer Lack Mexicana S.A. de C.V.

Temazcal No. 2, Colonia La Loma
C.P. 54060, Tlalnepantla, Estado de México
México

IATF USI THLLWK

Testing.